

**Committee: Open Spaces**

**Date: 1 December 2021**

**Title: Herne Hill Tree Safety Works**

**Purpose of Report**

To update members on the results of the tree safety survey

**Recommendation:**

- 1) For members to note the works identified by the survey from South Somerset District Council (SSDC) to be carried out.
- 2) For members to support a commission to SSDC to carry out similar surveys across our open spaces to help set a basis for our tree management programme

**Background:**

1. Ilminster Town Council, in common with other landowners, has a legal 'duty of care' to ensure that users and neighbours of its land are reasonably safe. The council must also ensure that risks to its employees and contractors are reduced as far as is 'reasonably practicable'.
2. Trees are constantly changing as they grow and vary with the seasons. They can also reach considerable size and can become damaged by the elements or affected by pests and diseases that can weaken them. Trees can fall over or lose branches meaning they have the potential to cause harm where they grow in areas of public access or within falling distance of structures or highways
3. The council's fundamental responsibility, in taking reasonable care as a responsible and prudent landowner, is to consider the risks posed by its trees. Therefore, SSDC were commissioned to carry out cursory visual assessment of Herne Hill walking routes to supplement in house inspections as described in the tree risk management plan.

**Report:**

4. The survey undertaken by SSDC did not include an evaluation of Ash dieback, however it looked at trees that present a risk to users of the three promoted routes and two picnic areas of Herne Hill.
5. 25 trees (or groups) were identified to have been showing signs of debility or structural weakness and remedial works have been advised (**APPENDIX 6a**).

6. A large proportion of these recommendations will require aerial tree works thus requiring a tree surgeons assistance, but the grounds team will take care of the recommendations that they are able to do in house.
7. Most work will include removing dead wood and reducing trees to alleviate stress on the trunks and forks and will show little to no visual impacts except from tree 18.
8. Tree 18 is one of the large pines in the fir pound on the top of the hill. It has a *phaeolus* Fungus also known as dyers polypore which causes butt rot in conifers thus a recommendation has been made to eco pole the tree, this will involve reducing the size of it to about 100m, removing the canopy and cutting the stem to mimic natural storm damage this will become a great habitat for birds and insects.
9. Most of the rest of these works are light touches and shouldn't have too much of a visual impact to the area
10. The table on APPENDIX 6a highlights all the other recommended works.

**Jake Taylor**  
**Countryside Manager**  
**1 December 2021**

| <b>Tree no</b> | <b>Location</b><br><i>By Reference to plan or onsite features</i> | <b>Species</b><br><i>Common or description</i> | <b>Height</b><br>(m) | <b>Condition</b><br><i>Brief Details of specific area of concern or observed defect</i> | <b>Action</b>  | <b>Priority</b><br><i>(High, Medium, Low)</i> |
|----------------|---|--|----------------------|---|--|---|
| 1              | Ridge Path entrance   | Oak  |                      | Dead wood Present   | Remove dead wood path side<br>(Complete 26/11/21)            |   |
| 2              | Ridge Path  | Ash  |                      | Ash stem leaning over pathway   | Removal of cankered stem pathway side<br>(Complete 26/11/21) |   |
| 3              | Ridge path by bench   | Oak  |                      | Dead wood present in tree   | Remove dead wood path side<br>(Complete 26/11/21)            |   |
| 4              | Red path on the corner  | Sycamore                                       |                      | Cavity present  | Reduction Path side by 4 m                                   |   |
| 5              | Red   | Ash  |                      | Tight union over pathway  | Reduction by 3 m   |   |
| 6              | Red trail on island in pathway                                    | Ash trees                                      |                      |   | Remove vegetation and ivy to allow further inspection        |   |
| 7              | Red trail   |  |                      | Mycelium on path side,  | Tree leaning away from trail                                 |   |
| 9              | Red trail   | London Plane                                   |                      | Hanging branches  | Remove hanging branches                                      |   |
| 10             | Red Trail   | Oak  |                      | Deadwood over exposed pathway.  | Retrench tree marked with dot<br>(Complete 26/11/21)         |   |

|    |                                 |           |  |   |   |  |
|----|---------------------------------|-----------|--|---|---|--|
| 11 | Red trail                       | Oak       |  | Deadwood hanging over pathway           | Remove hanging branches                                   |  |
| 12 | Sorbus                          | Rowen x 2 |  | Deadwood present                        | Remove deadwood bin and path side                         |  |
| 13 | Green trail                     | Oak       |  | Deadwood present                        | Shorten deadwood over pathway                             |  |
| 14 | Merge point of red/green/yellow | Oak       |  | Dead branch over pathway                | Remove large dead branch over pathway                     |  |
| 15 | Red/yellow                      | Oak       |  | dead branch over pathway                | Remove  |  |
| 16 | Yellow trail                    | Ash       |  | Ash. Torsion cracks on front stem.      | Reduce 4m over pathway                                    |  |
| 17 | Yellow Trail                    | Oak       |  | Large dead over pathway.                | Remove deadwood to boundary                               |  |
| 18 | Picnic area                     | Pinus     |  | Phaeolus bracket present                | Reduce to eco pole  |  |
| 19 | Picnic area                     | beech     |  | Juvenile Ganoderma's present.           | Reduce 2 metres. Monitor.                                 |  |
| 20 | Yellow Trail                    | Oak       |  | Cavity present and evidence of buckling | Reduce 2 x stems over pathway by 4m                       |  |
| 21 | Yellow                          | Lime      |  | Included bark. Tight fork.              | Subordinate pathway side stem by 3m to reduce end weight. |  |
| 22 | Yellow                          | Ash       |  | Hanging limb above pathway.             | Remove hanger   |  |

|    |                     |         |  |   |  |  |
|----|---------------------|---------|--|---|--|--|
| 23 | Yellow trail        | Red oak |  | Hanging branch/ dead limb over pathway.                     | Remove   |  |
| 24 | Yellow green        | Ash     |  | Grouped ash with deadwood over pathway                      | Remove   |  |
| 25 | Red/yellow junction | Pinus   |  | Phaeolus present at base, tree is leaning to opposite slope | Monitor dieback and weight reduction pathway side. |  |

| Priority   | Descriptor  |
|--|---|
| High   | A tree in poor condition or with significant defects adjacent to high value target, or tree in moderate condition adjacent to a very high value needing action soon |
| Medium   | A tree with defects adjacent medium value target, needing a planned and reasonable response   |
| Low  | A tree with limited defects or defects that you wish to be checked as you are unsure about there is significance adjacent low value target                          |
| <b>NOTE: If you are unsure about any feature that you observe then your concerns must be referred to competent person.</b> |   |