

Wharf Lane Recreation Ground Tuck Shop Refurbishment

Cabinet Requirements:

Plan Number	Total Required	Description	Purchase Code	Make	Total Price £
1	3*	Base cabinet with 1 drawer/2 doors/shelves	393.769.74	METOD/FORVARA	297
2	2	Base cabinet with 2 doors/shelves	793.830.91	METOD	96
3	1	Base cabinet for sink with 2 doors	593.727.05	METOD	72
4	1	Base cabinet with 1 drawer/1 door	993.454.37	METOD/FORVARA	62
5	1	Corner base cabinet with shelf	693.726.20	METOD	98
6	3	Base cabinet with 2 doors/shelves	593.668.32	METOD	228

Table 1: cabinet requirements

Sub total for cabinet requirements: £853

- may only require 2 if tall fridge freezer is installed by occupant reducing Grand total by £107

Additional requirements:

Total Required	Description	Purchase Code	Make	Total Price
12	Legs (4 per pack)	402.443.41	CAPITA	84
12	Handles (2 per pack)	003.364.32	GUBBARP	12
1	Sink*	291.581.89	VATTUDALEN	80
1	Tap*	304.423.89	GLYPEN	40
6	Worktop	502.427.23	LILLTRASK	150
4	Worktop cover strip	303.392.88	FIXA	16
4	Worktop support	702.746.28	FIXA	16

Table 2: Accessorises

- * Sink - 25 year guarantee
- Tap -10 year guarantee & energy efficient

Sub total for additional requirements: £398

Grand total: £1251 inc VAT

Other items to consider:

- Electric sockets will have to be moved higher up the wall so they are accessible above the counter tops (check commercial regs on height)
- Only 2 x 2 gang sockets in the area, this is not enough to run a café/tuck shop
- 1 electric socket is right next to the water inlets and grey water outlet (H&S)
- All doors to café/tuck shop open out. This may need rectifying for safety of users (possible secondary inside door at main entrance)
- No smoke detector
- Is a fire alarm required
- Are fire extinguishers required
- Oven / hob top
- Extractor fan for cooking smells
- Tiles falling off walls will require replacing (this could be done by taking existing tiles off the wall that will be behind cabinets and not seen)
- Electricity and water usage meters required (so occupant can be charged accordingly)
- UPVC door will require centre panel to be replace due to damage